

ACURA (USA / CAN) TLX TLX 3.5 (CAN) (2014-2020)



MOTOR J35Y6

Kapasitet: 4,3 liter, Filterkapasitet: 0,3 liter

BRUK

Fleksibel (vedlikeholdssystem om bord)

KLIMA

Moderat

PRODUKTANBEFALING 1

Presteza MSP 0W-20

Bytt hver 12 måneder

GIR AUTOMAT 9/1

Kapasitet: 3,3 liter

BRUK

Vanskelige forhold

KLIMA

Moderat

PRODUKTANBEFALING 1

SP Matic 4036

Bytt hver 48000 km

BRUK

Vanskelige forhold, kun første bytte

KLIMA

Moderat

PRODUKTANBEFALING 1

SP Matic 4036

Bytt hver 64000 km

BRUK

Fleksibel (vedlikeholdssystem om bord)

KLIMA

Moderat

PRODUKTANBEFALING 1

SP Matic 4036

HYDRAULISK BREMSESYSTEM

BRUK

Normal

KLIMA

Moderat

PRODUKTANBEFALING 1

Drauliquid DOT 3

Bytt hver 36 måneder

KJØLESYSTEM

Kapasitet: 0,72 liter (Beholder), Kapasitet: 8,4 liter (Servicepåfylling)

BRUK

Fleksibel (vedlikeholdssystem om bord)

KLIMA

Moderat

PRODUKTANBEFALING 1

Coolant SP 14+

ACURA (USA / CAN) TLX TLX 3.5 (CAN) (2014-2020)



KLIMAANLEGG-SYSTEM

Kapasitet: 475-525 gram

Vi er ikke i stand til å gi en standard anbefaling for denne komponenten. Ta kontakt med serviceavdelingen vår.

KLIMAANLEGGKOMPRESSOR

Kapasitet: 70-85 cm³

Vi er ikke i stand til å gi en standard anbefaling for denne komponenten. Ta kontakt med serviceavdelingen vår.

The data mentioned in this product information sheet is meant to enable the reader to orientate himself about the properties and possible applications of our products. Although this overview is composed with all possible care on the stated date, the compiler does not accept any liability for damages caused by incompleteness and/or inaccuracies in this information, especially when these are caused by obvious typing errors. The terms of delivery of the supplier apply to all product supplies. The reader is advised, especially for critical applications, to make the final product choice in consultation with the supplier. Due to continual product research and development, the information contained herein is subject to changes without notification.