

# BUICK (SGM) EXCELLE EXCELLE GT 1.4 TURBO (2015 AND AFTER)



**ENGINE** LFF Turbo  
Capacity: 4,4 liter (Service fill)

USE	CLIMATE
Flexible (max)	Moderate

PRODUCT RECOMMENDATION 1

**Presteza MSP 5W-30**

*Change every 5000 km/ 6 months*

**TRANSAXLE DCT CLUTCH PART**  
Capacity: 1,87-1,95 liter (Service fill)

USE	CLIMATE
Normal	Moderate

PRODUCT RECOMMENDATION 1

**SP Fluid 3013**

**TRANSAXLE DCT TRANSMISSION PART 7/1**  
Capacity: 2,35-2,55 liter (Service fill)

USE	CLIMATE
Severe	Moderate

PRODUCT RECOMMENDATION 1

**SP Matic 2072**

*Change every 72000 km*

## HYDRAULIC BRAKE SYSTEM

USE	CLIMATE
Normal	Moderate

PRODUCT RECOMMENDATION 1

**Drauliquid-LV Super DOT 4**

*Check every 10000 km/ 6 months, change every 30000 km/ 24 months*

**COOLING SYSTEM**  
Capacity: 6,2 liter (Service fill)

USE	CLIMATE
Normal	Moderate

PRODUCT RECOMMENDATION 1

**Coolant SP 15**

PRODUCT RECOMMENDATION 2

**Coolant SP 15+**

*Check every 10000 km/ 6 months, change every 240000 km/ 60 months*

PRODUCT RECOMMENDATION

# **BUICK (SGM) EXCELLE EXCELLE GT 1.4 TURBO (2015 AND AFTER)**



*The data mentioned in this product information sheet is meant to enable the reader to orientate himself about the properties and possible applications of our products. Although this overview is composed with all possible care on the stated date, the compiler does not accept any liability for damages caused by incompleteness and/or inaccuracies in this information, especially when these are caused by obvious typing errors. The terms of delivery of the supplier apply to all product supplies. The reader is advised, especially for critical applications, to make the final product choice in consultation with the supplier. Due to continual product research and development, the information contained herein is subject to changes without notification.*