

# DYNAPAC TANDEM DRUM VIBRATORY ROLLERS CC/CG/LA CC422 CUMMINS 4BTA 3.9 (62510843 ->)

**ENGINE** Cummins 4BTA3.9

USE	CLIMATE
Normal	Mediterranean

## PRODUCT RECOMMENDATION 1

**Multifleet SHPD 15W-40***Change every 200 hours*

USE	CLIMATE
Initial service	Mediterranean

## PRODUCT RECOMMENDATION 1

**Multifleet SHPD 15W-40***Change every 50 hours***TRANSMISSION**

USE	CLIMATE
Normal	Moderate

## PRODUCT RECOMMENDATION 1

**Gearlube GL-5 80W-90**

## PRODUCT RECOMMENDATION 2

**Unigear HS GL-3/GL-5 80W-90***Change every 2000 hours/ 12 months***HYDRAULIC SYSTEM**

USE	CLIMATE
Normal	Moderate

## PRODUCT RECOMMENDATION 1

**Perlus H 68****GREASE POINTS/NIPPLES**

USE	CLIMATE
Normal	Moderate

## PRODUCT RECOMMENDATION 1

**HT Q9 High Grade Grease**

## PRODUCT RECOMMENDATION 2

**Labora Grease****COOLING SYSTEM**

USE	CLIMATE
Normal	Moderate

## PRODUCT RECOMMENDATION 1

**Coolant -38 Organic NF**

## PRODUCT RECOMMENDATION 2

**Coolant -26**

# DYNAPAC TANDEM DRUM VIBRATORY ROLLERS CC/CG/LA CC422 CUMMINS 4BTA 3.9 (62510843 ->)



## DRUM

We are unable to give a standard recommendation for this component. Please contact our service department.

*The data mentioned in this product information sheet is meant to enable the reader to orientate himself about the properties and possible applications of our products. Although this overview is composed with all possible care on the stated date, the compiler does not accept any liability for damages caused by incompleteness and/or inaccuracies in this information, especially when these are caused by obvious typing errors. The terms of delivery of the supplier apply to all product supplies. The reader is advised, especially for critical applications, to make the final product choice in consultation with the supplier. Due to continual product research and development, the information contained herein is subject to changes without notification.*