

ACURA (USA / CAN) RDX TB3/4 RDX 3.5 I-VTEC V6[□] (2015-2018)



发动机UJ35Z6

润滑油容量: 4,3 升 (维修填充), 过滤器端盖: 0,3 升[□]

使用

气候

灵活 (最大)

温带

产品推荐 1

Presteza MSP 0W-20

自动驱动桥E/1

润滑油容量: 3,1 升[□]

使用

气候

严重, 仅限第一次改装

温带

产品推荐 1

SP Matic 4036

使用

气候

严重

温带

产品推荐 1

SP Matic 4036

使用

气候

灵活 (汽车式维修系统)

温带

产品推荐 1

SP Matic 4036

液压制动系统[□]

润滑油容量: 0-0 升 (最大和最小之间)[□]

使用

气候

正常

温带

产品推荐 1

Drauliquid DOT 3

ACURA (USA / CAN) RDX TB3/4 RDX 3.5 I-VTEC V6[□]
(2015-2018)



冷却系统 [□] 润滑油容量: 7.4 升 (维修填充) [□]		
使用 灵活 (汽车式维修系统)		气候 温带
产品推荐 1 Coolant SP 14+		

空调压缩机[□]
润滑油容量: 70-82 cm³[□]
我们无法为该零件提供标准建议。请与我们的服务部门联系。

空调系统[□]
润滑油容量: 430-480 克[□]
我们无法为该零件提供标准建议。请与我们的服务部门联系。

The data mentioned in this product information sheet is meant to enable the reader to orientate himself about the properties and possible applications of our products. Although this overview is composed with all possible care on the stated date, the compiler does not accept any liability for damages caused by incompleteness and/or inaccuracies in this information, especially when these are caused by obvious typing errors. The terms of delivery of the supplier apply to all product supplies. The reader is advised, especially for critical applications, to make the final product choice in consultation with the supplier. Due to continual product research and development, the information contained herein is subject to changes without notification.